




선풍기

모터를 이용하여 선풍기를 만든 것으로
감속기어나 가속기어를 사용하여
다양한 모양의 선풍기를 만들어보세요.




선풍기 부품리스트 | 구조물을 만들어 봅시다.

굵은돌기 수평셀 (2)	굵은 수평셀 (3)	굵은돌기 직각셀 (2)	굵은 직각셀 (5)	8돌기셀 (1)	7돌기셀 (2)	4돌기셀 (2)	6돌기셀 (1)	2돌기셀 (5)	기본셀 (5)	2단셀 (6)	굴절셀 (2)	연결셀 (2)
모터연결재 (1)	축45 (1)	간전지 6V 케이스 (1)	DC모터 (1)	온오프보드 (1)	연결재 (1)							




1 ★★★

- ×4
- ×1




2 ★★★

- ×2
- ×2
- ×2
- ×2




3 ★★★



4 ★★★

- ×2
- ×2
- ×2

4-1



4-2





그림 3번과 4-1번에서 만든 모형을 조립합니다.



5 ★★★

- ×1
- ×1
- ×1

5-1




5-2




5 ★★★

5-3




5-4

그림 5-2번과 5-3번에서 만든 모형을 조립합니다.



6 ★★★

6-1



6-2




같은 모형 2개를 만들어줍니다.


6-3



6-4



7 ★★★




8 ★★★




9 ★★★

9-1



9-2

완성



온오프보드 연결방법

